

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

October 7, 2005

Supervisor All

Mine Name: Fire Pit 1-4 Operator Name: Western Hills

> Ken Brown 288 West Center Kanab, Utah 84741

Inspector(s): Doug Jensen Other Participants: None Mine Status: Active **Permit number:** S/053/034 **Inspection Date:** Sept. 28, 2005

Time: 9:00 AM

Weather: Windy, warm

Elements of Inspection		Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (shafts, adits, trash, signs,	highwalls)			
3. Protection of Drainages / Erosion Control	ol			
Deleterious Material				
5. Roads (maintenance, surfacing, dust cor	trol, safety)			
6. Concurrent Reclamation				
7. Backfilling/Grading (trenches, pits, road	ls,			
highwalls, shafts, drill holes)		Ш		
B. Water Impoundments				
9. Soils				
0. Revegetation				
1. Air Quality				
2. Other				

Purpose of Inspection:

I have been unable to access this site the last couple of times that I was in the area due to a locked gate on the access road. The gate across the road was not put there by Western Hills but by the owner of a development company that owns land some distance below the site. I was able to access site by coming into the site from another direction.

Directions to Site: New access into the site is now by driving south through a new housing development. I GPS'd the route taken into the site and it is shown on the GPS map attached to this report.

Inspection Summary:

The road into the site is very rough due to the precipitation events that have taken place in the St. George area this year. The disturbances at the site have remained unchanged sine the last site visit in 1999. Much of these small excavations have become overgrown with volunteer vegetation. The operator is not removing any material from these areas.

Western Hills is presently removing rock from a side slope ~\frac{1}{4} of a mile below these disturbances. It appears that no mechanized equipment is being used to harvest the rock. There is minimal disturbance of the areas where the rock is presently being removed.

Inspection Date: September 28, 2005; Report Date: October 7, 2005

Page 2 of 2 S/053/034

Pictures were taken at the site and a GPS point was taken.

Conclusions and Recommendations:

Activity at the site appears to be very minimal. I will continue to monitor the site when I am in the area.

Inspector's Signature

Date: October 7, 2005


DJ:jb

cc: Western Hills, Inc, Operator

Rody Cox, BLM, St George FO

Attachment: GPS & Photos


O:\M053-Washington\S0530034-FirePit\inspections\insp-09282005.doc



OLD DISTURBANCE



LOWER PORTION OF SITE



Mine Name: Firepit Township 41 S Range 13 W Section 15 SLBM Mine Number: S0530034

Inspection Date Sept. 28, 2005 Map Produced by DKS

Acres Disturbed Acres Regraded Acres Seeded 0000

Road Acres Disturbed

Total Acres Distrubed 0


Acres Reclaimed Acres Excluded Acres Prelaw 000

Legend All items symbolized in legend may not be appear on map

Secondary Route

Main Dirt Road --- Trail Interstate
US Route
State Route - Primary Route ::::: Unimproved Road - County Boundary Township or range Line Township or range line: location doubtful BLM Leases
CommunityPit SITLA Mineral Leases

DOQ imagery date 2004



Dept. of Natural Resources Division of Oil, Gas, and Mining Mineral Mines Program

Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content. Verify Scale

1:7,500 1 inch equals 625 feet